

# Product Safety Recall

## Product Information

### **Product Part Number and Description**

K12061 Kincrome **1800kg Trolley Jack**

Batch #: AIMC36837, AIMC33966, AIMC22420, AIMC48035

### **Defect:**

The jack failed to meet the serviceability requirements of section 5.4a, 5.5, 6.4, 6.7a and 6.7x

### **Effected Products:**

K12061 batch #'s: AIMC36837, AIMC33966, AIMC22420, AIMC48035;  
supplied from April 2013

## **What Should Consumers do;**

### **Consumer Actions:**

Stop using your jack immediately and return to the place of purchase, for an exchange or full refund.

## **Further Information:**

### **Supplier Information:**

Kincrome Tools & Equipment  
3 Lakeview Drive  
Scoresby VIC 3179  
Ph: (03) 97307100

### **Supplier Web Site:**

[www.kincrome.com.au](http://www.kincrome.com.au)

### **Supplier Contact:**

Jason Rae



See [www.recalls.gov.au](http://www.recalls.gov.au) for  
Australian Product Recall Information